PHRF San Diego 1220 Rosecrans St PMB #149 San Diego, CA 92106 www.phrfsandiego.org

PHRF San Diego Rating Certificate 2023



| MEMBER INFORMATION | | | | YACHT INFORMATION | | | |
|------------------------------|----------|--------------------|-----------------------------|-----------------------|------|-------------------------------|-----------------|
| Name Paul & Margo Hemond | | | | Name Falcon | | | |
| Cell | | | Sail # 46854 | | | | |
| Email | | | | CF/Documentation 4115 | | | |
| PHRF SAN DIEGO HANDICAPS | | | PHRF SAN DIEGO RACING CLASS | | | | |
| Windward-Leeward (Buoy) | | 96 | | NA | | | |
| General Purpose (RLC) | | 81 | | | | | |
| Offwind/Point-to-Point (OWC) | | 81 | | | | | |
| YACHT DATA | | RIG AND | | SAIL PLAN | | OTHER INFORMATION | |
| Manufacturer | Hobie | Rig Type | | Sloop | | Performance Factor OLD | 6.50 |
| Model | 33 | Mast Type | | Fractional | | Performance Factor NEW | 9.17 |
| Year Built | 1983 | Mast Size | | Standard | | Performance Factor SoCal 3.63 | |
| Hull # | 4115 | I | 33.8 | Р | 35 | | |
| Hull Material | Glass | J | 12.4 | E | 12.5 | Non-Spin Offset | 25.45 |
| HULL SPECIFICATIONS | | Headsail Size | | 155 | | | |
| LOA | 33 | Rated Sail Area | | 630.36 | | Lifelines/Pulpit | PERMANENT/FIXED |
| LWL | 30.5 | Off-Wind Sail Area | | 950.25 | | Category Limitation | none |
| Beam | 8 | Hydraulics | | none | | Reported Modifications | |
| Draft | 5.5 | | SYMMETRIC | L SPINNAKER | | none | |
| Displacement | 4000 | SMW | 23.1 | SL | 36.6 | 1 | |
| Ballast Keel | 1800 | Pole/SPL | 12.8 | SF | 22.5 | | |
| Keel Type | Fin | , , | Area | 679.28 | | | |
| Keel Material | Lead | | ASYMMETRIC | AL SPINNA | KFR | | |
| PROPULSION | | SLU | 39.9 | SF | 23.1 | | |
| Aux/Engine | Outboard | SLE | 36.1 | ASMW | 23.1 | | |
| Prop Type | None | TPS | 12.8 | ISP | 36.8 | | |
| Blades | 0 | | Area | 731.50 | _0.0 | | |

Important Notice about your ratings in San Diego!

For your handicap to remain valid, you must notify PHRF San Diego in writing of any reportable modifications to your yacht. Failure to follow this procedure will carry an automatic 30 DAY SUSPENSION from racing in PHRF races, followed by a San Diego Handicap Board review to determine the extent of additional equipment TIME ALLOWANCE adjustments to be included in that yacht's base handicap.